Document number:	B118_CT004 rev. 9
Dated:	24-Jan-25
Expiry date:	24-Jan-27

IEC 61508 Functional Safety Capability Statement

Tyco Fire & Security GmbH (TFSG), Generation 6 PH Detectors

Manufacturer:	Tyco Fire & Security GmbH (TFSG) Victor Von Bruns-Strasse 21, 8212 Neuhausen am Rheinfall, Schaffhausen, Switzerland
Product:	Fire Detector
Model:	Generation 6 850PH, Generation 6 851PH, Generation 6 851PHN, Generation 6 856PH, Generation 6 840PH, Generation 6 830PH, Generation 6 835PH, Generation 6 855PH, Generation 6 FC460PH, Generation 6 4098-6251 Optical Heat and Generation 6 4098-6231 Optical Heat

Application:	Low Demand Mode Safety Instrumented Function
Safety Function:	Upon detectors inability to detect and process alarms over the addressable system, action is initiated (Logic solver and final element subsystems not part of this analysis)
Applied standard:	IEC 61508 Ed2 2010 Parts 1-3
Systematic Capability:	Not Assessed
Applicable report:	Generation 6 PH Review Report Iss3, by TFSG dated 02/07/2012 Generation 6 PH FMEDA Iss2, by TFSG dated 06/06/2012

Assessment Route:	1_H
Hardware Fault Tolerance:	0
Type:	B
Application restrictions:	None

Model No.	λDU (/hr)	λDD (/hr)	λS (/hr)	SFF	SIL AC (HFT = 0)
850PH / 855PH Multi-sensor Detector with s/c Isolator	3.2E-07	4.3E-06	4.5E-07	93%	SIL 2
851PH Multi-sensor Detector with s/c Isolator	3.2E-07	4.3E-06	4.5E-07	93%	SIL 2
851PHN Multi-sensor Detector with s/c Isolator	3.2E-07	4.3E-06	4.5E-07	93%	SIL 2
856PH Multi-sensor Detector with s/c Isolator	3.2E-07	4.3E-06	4.5E-07	93%	SIL 2

© Copyright 2025 by The ERM International Group Limited and/or its affiliates ('ERM'). All Rights Reserved.

Document number:	B118_CT004 rev. 9
Dated:	24-Jan-25
Expiry date:	24-Jan-27

Model No.	λDU (/hr)	λDD (/hr)	λS (/hr)	SFF	SIL AC (HFT = 0)
840PH Multi-sensor Detector	3.2E-07	4.3E-06	4.5E-07	93%	SIL 2
830PH / 835PH Multi-sensor Detector	3.2E-07	4.3E-06	4.5E-07	93%	SIL 2
FC460PH Multi-sensor Detector	3.0E-07	4.1E-06	4.5E-07	93%	SIL 2
4098-6251 Optical Heat Multi-sensor Detector with s/c Isolator	3.2E-07	4.3E-06	4.5E-07	93%	SIL 2
4098-6231 Optical Heat Multi-sensor Detector	3.2E-07	4.3E-06	4.5E-07	93%	SIL 2

SIL AC (Architectural Constraints): Represents the maximum allowable SIL of each hardware element, assuming Hardware Fault Tolerance (HFT) = 0.

It should be noted that for a device to meet a required SIL that the SIL AC and SIL SC of the device needs to both be met. In addition to this, the required Probability of Failure on Demand (PFD) value for the complete Safety Instrumented Function (SIF) needs to adhere to the SIL PFD ranges.

IMPORTANT: It should be noted that this assessment considers only the Tyco Fire & Security GmbH (TFSG), Generation 6 PH Detectors. It does not cover opening and closing time requirements and a random hardware failures assessment must be conducted for the entire safety function for each application as per the appropriate Safety Requirements Specification.

The Tyco Fire & Security GmbH (TFSG), Generation 6 PH Detectors have been assessed and are considered capable for use in a low demand mode safety function up to (and including) SIL 2 with regards to random hardware failures and architectural constraints.

Note 1: The SIL of a complete SIF (sensor, logic solver and final element subsystems) must be verified to calculate the required PFD / Probability of Failure per Hour (PFH), considering any redundancy, Proof Test Interval (PTI), Proof Test Coverage (PTC), Mission Time and Mean Time To Restoration (MTTR) for all elements included in the SIF. Each subsystem should be verified to ensure compliance with the minimum HFT requirements.

Chantal Sealey FS Eng (TÜV Rheinland) Assessor chantal.sealey@erm.com	Simon Burwood FS Expert (TÜV Rheinland) Assessment Authority simon.burwood@erm.com