



ENGINEERING SAFETY CONSULTANTS

The Global Provider of Functional Safety Expertise and Technical Consultancy

Certificate of Conformity to IEC 61508 Safety Integrity Level (SIL) 2

Functional Safety of Safety-Related Programmable Electronic Systems

The **Apollo Fire Detectors Ltd, Manual Call Points** have been assessed and are considered capable for use in a low demand Safety Function up to SIL 2, in terms of random failure rate and architectural constraints.

The assessment was based on the assumptions, data provided, and recommendations given in:

- **Technis Report No. T616 Issue 2.0;**
- **Renewal Letter from Apollo Fire Detection Ltd, signed by Chris Ellis, Head of Compliance, dated 22nd September 2020;**
- **Manual Call Points 55100-940 & 55100-940APO Update Letter from Apollo Fire Detection Ltd, signed by Mark Schofield, Systems Engineer, dated 20th February 2019.**

However, although not included in the initial assessment, 55100-940 and 55100-940APO Intrinsically Safe Call Points (SIL) are the same in functionality and design as the 55000-940CD SIL Intrinsically Safe Call Point with the only difference being the label.

The certified devices can only achieve SIL 2 if used in conjunction with a fire alarm control panel that supports all elements of the Apollo protocol, including full fault diagnostic.

Products covered by this certificate should carry the applicable Technic report number.

The system assessed comprises the following modules:

- 58100 – 908CD SIL Isolated Call Point
- 55000 – 940CD SIL Intrinsically Safe Call Point
- 55100 – 940APO Intrinsically Safe Call Point (SIL)

The assessment was carried out to determine compliance IEC 61508 with regards to:

- Random Hardware Failures (providing a minimum proof test interval of one year and a repair time of a detected failure of 24 hours has a PFD of <E-04), and;
- Architectural Constraints (Type B, SFF >92%).

IMPORTANT: It should be noted that this assessment does not include confirmation of the response time of the device. For response times (along with any relevant assumptions) reference should be made to the Safety Manual of each device and the total SIF response time **MUST** be compared against the process safety time for the specific application.

Chairman: Kenneth G L Simpson
Member of the IEC 61508 committee
Assessment Date: February 2012

Renewal Date: October 2020, valid to October 2022

Certificate: A191_CT003 rev. 5

ENGINEERING SAFETY CONSULTANTS LTD
is ISO9001-certified by Global Group, itself a
UKAS-accredited ISO9001 certification
body

Reg: 12Q12086

ENGINEERING SAFETY CONSULTANTS LTD

Tuition House

27-37 St George's Road Wimbledon London SW19 4EU UK

Telephone/Fax: +44 (0)20 8542 2807

E-Mail: info@esc.uk.net Web: www.esc.uk.net

Registered in England and Wales: 7006868

Registered Office: 27-37 St George's Road Wimbledon London SW19 4EU